## This is to certify that Countrywide Fire Services

has inspected the equipment listed below and that they have been inspected and serviced in accordance with British Standards 5306 pt 3

CUSTOMER: Central Properties SERVICE DATE: 23/10/2013 CONTACT REF: Jim / Lara EXPIRY DATE: 22/10/2014

ACCOUNT REF: 13713

Number	Location	Equipment	G.W.O.	Attention	Fitted
				Req.	
1	Kitchen, 11 Naburn Street, M13 0FL	Fire Blanket	Yes	No	Yes
2	Kitchen, 3 Denham Street, M13 0FJ	Fire Blanket	Yes	No	Yes
3	Kitchen,8 Denham Street, M13 0FJ	Fire Blanket	Yes	No	Yes
4	Kitchen, 14 Denham Street, M13 0FJ	Fire Blanket	Yes	No	Yes
5	Kitchen, 13 Welby Street M13 0EL,	Fire Blanket	Yes	No	Yes
6	Kitchen,15 Welby Street, M13 0EL	Fire Blanket	Yes	No	Yes
7	Kitchen, 18 Welbey Street, M13 0EL	Fire Blanket	Not Inspected	See Below	N/A
8	Kitchen, 15 Eston Street, M13 0FF	Fire Blanket	Yes	No	Yes
9	Kitchen, 18 Eston Street, M13 0FF	Fire Blanket	Yes	No	Yes
10	Kitchen, 90 Ealing Avenue, M14 5WF	Fire Blanket	Yes	No	Yes
11	Kitchen,3 Fenella Street, M13 0DT	Fire Blanket	Yes	No	Yes
12	Kitchen, 65 Richmond Grove, M13 0DH	Fire Blanket	Yes	No	Yes
13	Kitchen,11 Hathersage, Road, M13 0EJ	Fire Blanket	Yes	No	Yes
14	Kitchen, 31 Hathersage Road, M13 0EJ	Fire Blanket	Yes	No	Yes
15	Kitchen. 41 Hathersage Road, M13 0EJ	Fire Blanket	Yes	No	Yes
16	Kitchen, 49 Hathersage Road, M13 0EJ	Fire Blanket	Yes	No	Yes
17	Kitchen, 12 Argyle Avenue,M14 5PX	Fire Blanket	Yes	No	Yes
18	Kitchen, 14 Argyle Avenue, M14 5PX	Fire Blanket	Yes	No	Yes
19	Kitchen, 18 Scarsdale Road, M14 5PR	Fire Blanket	Yes	No	Yes
20	Kitchen, 59 Denison Road, M14 5LZ	Fire Blanket	Yes	No	Yes

NUMBER = EQUIPMENT I.D LOCATION = POSITION OF EQUIPMENT FITTED CORRECTLY WALL MOUNTED  $G.W.O = IN \; GOOD \; WORKING \; ORDER$   $ATTENTION \; REQ. = CORRECTIVE \; ACTION \; REQ$ 

Number	Corrective Action Taken or Required		
7	This property is under renovation, the Fire Blanket will be refitted on completion of renovation.		