



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

18 Scarsdale Road 8

Certificate No: Cert.1625

Engineers Details								Installation Details						Client Details						
Trading Title		PLUMBANDHEAT.ME						allation	18 Scarsdale Road Central Properties				Client		Central Properties					
Address		132-134						dress	18 Scarsdale Road Victoria Park					Address	100 E	100 Birchfields Road				
		Great Ancoats Street							Manchester					Fallo	Fallowfield					
		Manchester													Manchester					
		Post Code: M4 6DE						Post Code: M14 5PR							Post Code: M146PH			н		
One Octo N		F50072 Telephone No. 07020954272					╡	Telephone No:				Telephone No: 0161224304								
Gas	s Safe No:	559973 Telephone No: 07929854373					lei	ephone N	10:					Telephone No: 0161224304			14			
Appliance Details							Inspection Details										•			
	Locatic	Location		rpe Ma	ake	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Verinitation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Cella	Cellar		boiler Wor	cester	enstar 30 CDI covention	0.0001	0.0005	18.3 mb	48	YES	RS	YES	YES	YES	YES	PASS	NO	YES	
2																				
3																				
4																				
5																				
Fa	Faults/Notes							Remedial Work Taken									Warni	Warning Notice Fixed		
1	Note, Hot water system, unvented cylinder. Water discharging through tun dish and valve fault. Both require attention							zone Advised landlord										NA		
2																				
3																				
4																	+			
5	-																+			
		wal Mak sa		_			-													
	ergency Cont essible:	roi vaive	YES	Gas Tigh	tness Sa	tisfactory: YES	eport Issued By: Gas ID Number:									4959083				
Contractalistics Discussed Visual Inspection Satisfactory									Name: Robert Whiteoak Signed: Date:								Thu-13-10-2022			
Nun	nber of Appli	ances Te	sted: 1	Equi	potential	Bonding: YES	1		ort Received By:											
NEXT INSPECTION DUE ON OR BEFORE: Fri-13-10-2023 Installation Pass: YES							1	me: Signed: Date:								Thu-13	Thu-13-10-2022			
CO Alarm fitted, working & in the YES Smoke alarm fitted & working? YES This Gas Safety Report was created by Gas Checker Software a same room as appliance? For appliances not owned by the Landlord the recorded 'Appliance Safe' response.												oftware all rights r e' response is bas	eserved wv ed on a visu	vw.gaschecker.co. ual check for obvio	.uk ous defects o	only.				