



## Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

Certificate Reference

64 Finchley Road 9

Certificate No: Cert.1853

Engineers Details						Insta	Installation Details						Client Details					
Trading Title Address		PLUMBANDHEAT.ME  132-134					Installation Address		64 Finchley Road Central Properties 64 Finchley Road Fallowfield						al Properties			
														100 B	100 Birchfields Road			
		Great Ancoats Street							Manchester					Fallov	Fallowfield			
		Manchester										Manchester						
		Post Code: M4 6DE						Post Code: M14 6EW						Post Code: M146PH				н
													J					
Gas Safe No:		559973 Telephone No: 07929854373				Tel	ephone N	o:				Telephone No: 0161224304			14			
Appliance Details						Inspection Details												
	Locatio	on	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (VO = Vieual Improder) Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitche	en	Combi boiler	Worcester	eenstar 34 CDi Classic E	0.0001	0.0006	16 mb	54	YES	RS	YES	YES	YES	YES	PASS	NO	YES
2																		
3																		
$\vdash$																	-	
4																		
5																		
Faults/Notes							Remedial Work Taken								Warning Notice Fixed			
1																		
2																		
3																		
4																		
5																		
	l ergency Cont	trol Valve		Si	gnature	s												
	essible:		YES		Report Issued By:									495908	3			
Gas	Installation F	Pipework	Visual Inspection Sa	Na	Name: Robert Whiteoak Signed: Signed:							<b>→</b>	Date:	Fri-13-1	0-2023			
Nur	nber of Appli	ances Te	sted: 1	Equipotential	Bonding: YES	Re	Report Received By:								_	•		
NEXT INSPECTION DUE ON OR BEFORE: Sun-13-10-2024 Installation Pass: YES						1	ıme: [	Signed:							Date:	Fri-13-1	0-2023	
СО	CO Alarm fitted & working?  YES Smoke alarm fitted & working? YES  This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious details.												oftware all rights re e' response is base	served wv	vw.gaschecker.co. ual check for obvio	.uk ous defects c	only.	