



# Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.  
This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

3 Tait Mews 11

Certificate No: Cert.2305

## Engineers Details

Trading Title **PLUMBANDHEAT.ME**

Address **Piccadilly Business Centre  
Aldow Enterprise Park  
Manchester**

Post Code: M12 6AE

Gas Safe No: **559973**

Telephone No: **07929854373**

## Installation Details

Installation Address

**3 Tait Mews Central Properties  
3 Tait Mews  
Heaton Mersey  
Stockport**

Post Code: SK4 3DX

## Client Details

Client Address **Central Properties  
100 Birchfields Road  
Fallowfield  
Manchester**

Post Code: M146PH

## Appliance Details

## Inspection Details

	Location	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (kW) or Operating Pressure (Mbar)	CO Reading (ppm)	Appliance Inspected (YES/NO/NA) <small>(NO is Not Inspected Only)</small>	Flue Type (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO/NA)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Combi boiler	Glowworm	Easicom 24	0.0002	0.0007	20.9 mb	62	YES	RS	YES	YES	YES	YES	PASS	NO	YES
2	Kitchen	Hob	Range	No Name	null	null	8.11 kw	0	YES	FL	YES	YES	YES	NA	NA	NO	YES
3	Lounge	Fire	Valor	Victorian Classic	0	0	19.5 mb		YES	OF	YES	YES	YES	YES	PASS	NO	YES
4																	
5																	

## Faults/Notes

## Remedial Work Taken

## Warning Notice Fixed

1		
2		
3		
4		
5		

Emergency Control Valve  
Accessible: **YES**

Gas Tightness Satisfactory: **YES**

**YES**

## Signatures

Gas ID Number: **5797211**

Gas Installation Pipework Visual Inspection Satisfactory:

**YES**

Signed:

Date: **Fri-10-10-2025**

Number of Appliances Tested: **3**

Equipotential Bonding: **NO**

Report Received By:

Name: **Robert Whiteoak**

NEXT INSPECTION DUE ON  
OR BEFORE:

**Sat-10-10-2026**

Installation Pass: **YES**

Name:

Signed:

Date: **Fri-10-10-2025**

CO Alarm fitted & working?

**YES**

Smoke alarm fitted & working? **YES**