Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference: 3 Tait Mews 12

Certificate No: Cert.2506

Engineers Details

Trading Title: PLUMBANDHEAT.ME

Address: Piccadilly Business Centre, Aldow Enterprise Park, Manchester, Post Code: M12 6AE

Gas Safe No: 559973

Telephone No: 07929854373

Installation Details

Installation Address: 3 Tait Mews Central Properties, 3 Tait Mews, Heaton Mersey, Stockport, Post Code: SK4 3DX

Telephone No:

Client Details

Client Address: Central Properties, 100 Birchfields Road, Fallowfield, Manchester, Post Code: M146PH

Telephone No: 01612243044

Appliance Details / Inspection Details

	Location	Appliance Type	Make	Model	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure (Mbar)	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/IO) (I/O – Visual Inspection Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Combi boiler	Glowworm	Easicom 24	0.0002	0.0009	20.9 mb	81	YES	RS	YES	YES	YES	YES	PASS	NO	YES
2	Kitchen	Hob	Range	No Name	null	null	8.26 kw	0	YES	FL	YES	YES	YES	NA	NA	NO	YES
3	Lounge	Fire	Valor	Victorian Classic	0	0	19.5 mb		YES	OF	YES	YES	YES	YES	PASS	NO	YES
4																	
5																	

Faults/Notes / Remedial Work Taken / Warning Notice Fixed

	Faults/Notes	Remedial Work Taken	Warning Notice Fixed
1			
2			
3			
4			
5			

Emergency Control Valve Accessible: YES

Gas Tightness Satisfactory: YES

Gas Installation Pipework Visual Inspection Satisfactory: YES

Number of Appliances Tested: 3

Equipotential Bonding: NO

NEXT INSPECTION DUE ON OR BEFORE: Sun-10-10-2027

Installation Pass: YES

CO Alarm fitted & working? YES

Smoke alarm fitted & working? YES

Signatures

Report Issued By:

Name: Robert Whiteoak

Signed: 

Date: Fri-02-10-2026

Gas ID Number: 6020636

Report Received By:

Name:

Signed:

Date: Fri-02-10-2026

This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk

For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.